

IN THE ABSTRACT

Kindly amend the abstract as follows:

~~An apparatus for universal mounting of a computer system in a vehicle includes a~~ A mount ~~which~~ is fixed to the floor of a vehicle, and ~~which~~ supports a computer/display unit by means of an indexing cylinder assembly. ~~The user is provided with the capability of rotating the computer/display unit~~ can be rotated horizontally in steps about the indexing cylinder assembly so that it can be easily positioned for use by the driver or the passenger in the vehicle, ~~and of adjusting the~~. ~~The~~ computer/display unit can be adjusted vertically to suit the needs of the user while not interfering with the user's ability to see the road. The indexing cylinder may be mounted on either side of an upright member so as to provide selection of left or right positioning of the computer equipment. ~~The apparatus includes a~~ A bearing rod ~~which~~ runs up the side of a computer equipment holding frame, and ~~which~~ can be used to adjust the pressure point on the dashboard, thereby providing stabilization of the computer equipment.

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**